


# Lecture 10

## Thermal Sensors

# DS1620




- Digital thermometer
  - Provides 9-bit temperature readings
  - Temperature range from  $-55^{\circ}\text{C}$  to  $125^{\circ}\text{C}$
  - Acts as a thermostat


# Detail Description

PIN	SYMBOL	DESCRIPTION
1	DQ	<b>Data Input/Output pin</b> for 3-wire communication port.
2	CLK/ $\overline{\text{CONV}}$	<b>Clock input pin</b> for 3-wire communication port. When the DS1620 is used in a stand-alone application with no 3-wire port, this pin can be used as a convert pin. Temperature conversion will begin on the falling edge of $\overline{\text{CONV}}$ .
3	$\overline{\text{RST}}$	<b>Reset input pin</b> for 3-wire communication port.
4	GND	<b>Ground pin.</b>
5	T <sub>COM</sub>	<b>High/Low Combination Trigger.</b> Goes high when temperature exceeds TH; will reset to low when temperature falls below TL.
6	T <sub>LOW</sub>	<b>Low Temperature Trigger.</b> Goes high when temperature falls below TL.
7	T <sub>HIGH</sub>	<b>High Temperature Trigger.</b> Goes high when temperature exceeds TH.
8	V <sub>DD</sub>	<b>Supply Voltage.</b> 2.7V – 5.5V input power pin.

# DS1620 with BS2



# Programming for DS1620 1



# Programming for DS1620 2

high 13 ← - - - - - Ready to start

Shiftout 15,14,lsbfirst,[238] ← - - Start conversion

low 13

Temploop:

high 13

shiftout 15,14,lsbfirst,[170] ← - - Send “get data” command



shiftin 15,14,lsbpre,[x] ← - - - - Get the data

low 13

degC=x/2

Goto Temploop


# AD592



\* PIN 2 CAN BE EITHER ATTACHED OR UNCONNECTED  
BOTTOM VIEW

- Analog temperature sensor
  - Provides an output current proportional to absolute temperature
  - Temperature range from  $-25^{\circ}\text{C}$  to  $105^{\circ}\text{C}$
  - Acts as a thermostat
  - Extended out away from the recording instruments

# Temperature Probe with AD592





- The part needs to be protected before being inserted into liquid






# How to Make Temperature Probe 1




1. Identify the AD 592's (-), NC, and (+) pins from this picture as viewed from the bottom
2. Slip the solder sleeve over the black wire and pin 3 (-)
3. Slip another solder sleeve over the red wire and pin 1 (+)
4. Heat up the connections until the wires are joined

# How to Make Temperature Probe 2




5. Slip the heat shrink tubing over the entire package
6. Fasten the package with a heat gun, and while it's still hot clamp the top portion to ensure that it stays shut

# AD592 with BS2



# Caution!!



- Be careful when you put your finger on it
- Specially for a big finger




# Temperaure Sensors Experiments

Experiments	Chapters
What's micro controller	
Basic A and D	
Process Control	
Boe Bot Robotics	
Smart Sensors	
Others	

# Lecture 11

## Robotics

# Robots




# Definition of Robot

- First introduced by Karel Capek in a 1920
- Definition of robot
  - Reprogrammable
  - Multifunctional manipulator
  - Designed to move material, parts, tools or specialized devices
  - Through variable programmed motions for the performance of a variety of tasks
  - Robot Institute of America, 1979






# Sensors




Devantech SRF04



# Actuators

- Actuators used in robotics is almost always combinations of different electro-mechanical devices
  - Stepper motor
  - AC servo motor
  - Brushless DC servo motor
  - Brushed DC servo motor





Hydraulic Motor



Stepper Motor




Pneumatic Motor




Servo Motor

# Controller



**RoboBoard Robotics  
Controller**




**BASIC Stamp 2 Module**

# The Interface Units

Interfacing with the external world (sensors and actuators)



Analog to Digital Converter



Operational Amplifier

# What Can a Robot Do?

- Industrial Robots


1. Material Handling
2. Material Transfer
3. Machine Loading and/or Unloading
4. Spot Welding
5. Continuous Arc Welding
6. Spray Coating
7. Assembly
8. Inspection



Material Handling Manipulator



Spot Welding Manipulator



Assembly Manipulator

# How to Modify Servo Motor






# Prepare All the Tools







# Open Cover



# Take All Gears Out




# Take Pot Drive Plate Out




Don't forget  
to remove it



# Cut Tab off the Surface of the Gear




Before



After

# Servo Calibration



**low 12**


**loop:**

**pulsout 12, 750**

**pause 20**

**goto loop**

# Fully Assembled Boe-Bot



# Robot Experiments

Experiments	Chapters
What's micro controller	
Basic A and D	
Process Control	
Boe Bot Robotics	1, 2, 3, and 4
Smart Sensors	
Others	